




Spartan 9500 Winch Assembly Drawing



WINCH PARTS LIST

No.	Part #	Qty	Description	Remark
1	950001	3	Terminal Protect	
2	950100	1	Motor Assembly	
3	950002	6	Cap Screw M10 x 35	
4	950003	6	Lock Washer Φ10	
5	950004	6	Think Flat Washer Φ10	
6	950005	4	Hex Nut M10	
7	950200	1	Break / Shaft Assembly	
8	950006	2	Bushing—Drum	
9	950007	2	Tie Bar	
10	950008	2	Ring Seals	
11	950009	1	Screw M8 x 10	
12	950010	4	Lock Washer Φ8	
13	950011	4	Cap Screw M8 x 30	
14	950300	1	Drum Assembly	
15	950012	8	Screw M5 x 20	
16	950013	8	Lock Washer Φ5	
17	950014	1	End Bearing	
18	950015	1	Gasket	
19	950016	1	Gear—Ring	
20	950400	1	Gear Carrier Assembly (Output)	
21	950500	1	Gear Carrier Assembly (Intermediate)	
22	950600	1	Gear Carrier Assembly (Input)	
23	950017	1	Gear—Input Sun	
24	950018	1	Trust Washer	
25	950019	1	Gear—Housing	
26	950020	1	Clutch Screw	
27	950021	1	Ring Seals	
28	950022	1	Clutch Cover	
29	950023	1	Clutch Handle	
30	950024	2	Locknut M10	
31	950700	1	Roller Fairlead	
32	950025	1	Mounting Channel	By Choice
33	950950	1	Remote Control Switch (RC3)	
34	950900	1	Cable Assembly	
35	801000	1	Control Box	
36	950026	2	Screw M5×16	
37	950027	2	Lock Washer Ø5	
38	950028	2	Block	